# **Botus Fleming Parish Council Asset Audit Report**

(This audit does not include any aspect of the Playing Field which is audited separately)

DATE OF AUDIT: 14/08/2023		AUDITED BY: S. White							
	-								
Item	Area		Condition	Action Required					
1									
Life Belt	Moditonham Quay		Good	None					
Notes:									
Parish Pound	Botus Fleming		Good	None					
Notes:									
Bus Shelter	Hatt		No change	None					
Railings and Signage	Hatt Roundabout		No change	None					
Play Equipment	Recreation Field		See Appendix A						
Notes:									
Notice Board	Botus Fle	eming	Good	None					
	Hatt		Good	None					
Notes:									

## **Botus Fleming Parish Council Asset Audit Report**

(This audit does not include any aspect of the Playing Field which is audited separately)

DATE OF AUDIT: 14/08/2023		AUDITED BY: S. White						
Item	Area		Condition	Action Required				
1 1								
Salt Grit Bins	Hatt Sunnybanks		1/2 Full	None				
	Hatt Vollards Lane		1/2 Full	None				
	Road, Hatt To Botus Fleming		Full	None				
	Botus Fleming Crossroads		1/4 Full	None				
Notes:								
Benches	Moditonh	am Quay	Good	None				
	Road, Hatt To Botus Fleming		Fair	None				
	Recreation Field 1		Fair	None				
	Recreation Field 2		Fair	None				
Picnic Benches	Recreation Field		Good	None				
Notes:								
Laptop	Parish Clerk		No change	None				
Printer	Councillor/Auditor		No change	None				

### **Botus Fleming Parish Council Asset Audit Report**

(This audit does not include any aspect of the Playing Field which is audited separately)

#### Appendix A

#### Checklist For Play Equipment

Maintenance Check	Week 1	Week 2	Week 3	Week 4	Comment
Check Rotating Parts	23/7	29/7	6/8	12/8	
Check Swing Chain Links/Shackles/Seats	23/7	29/7	6/8	12/8	
Check Bolts/Fixings/Ball Joints	23/7	29/7	6/8	12/8	
Check For Loose/Missing Parts	23/7	29/7	6/8	12/8	
Check Plastic/Rubber Parts	23/7	29/7	6/8	12/8	
Check For Damage/Obstruction/Corrosion	23/7	29/7	6/8	12/8	
Check Safe Surfacing	23/7	29/7	6/8	12/8	

Notes: The ground in front of the entrance to the train play equipment has become deeply rutted by wear beyond the end of the safety matting.