

Botus Fleming Parish Council Asset Audit Report

(This audit does not include any aspect of the Playing Field which is audited separately)

DATE OF AUDIT: 21/09/2026	AUDITED BY: S. White
------------------------------	-------------------------

Item	Area	Condition	Action Required
------	------	-----------	-----------------

Life Belt	Moditonham Quay	Good	None
-----------	-----------------	------	------

Notes:

Parish Pound	Botus Fleming	Good	None
--------------	---------------	------	------

Notes:

Bus Shelter	Hatt	Good	None
Railings and Signage	Hatt Roundabout	No Change	None
Play Equipment	Recreation Field	See Appendix A	

Notes:

Notice Board	Botus Fleming	Good	None
	Hatt	Good	None

Notes:

Botus Fleming Parish Council Asset Audit Report

(This audit does not include any aspect of the Playing Field which is audited separately)

DATE OF AUDIT: 21/09/2024	AUDITED BY: S. White
------------------------------	-------------------------

Item	Area	Condition	Action Required
------	------	-----------	-----------------

Salt Grit Bins	Hatt Sunnybanks	3/4 Empty	None
	Hatt Vollards Lane	3/4 Empty	None
	Road, Hatt To Botus Fleming	Empty	None
	Botus Fleming Crossroads	Full	None

Notes:

Benches	Moditonham Quay	Fair	None
	Road, Hatt To Botus Fleming	Fair	None
	Recreation Field 1	Fair	None
	Recreation Field 2	Poor	None
Picnic Benches	Recreation Field	Fair	None

Notes: New benches awaiting installation.

Laptop	Parish Clerk	No Change	None
Printer	Councillor/Auditor	No Change	None

Botus Fleming Parish Council Asset Audit Report

(This audit does not include any aspect of the Playing Field which is audited separately)

Appendix A

Checklist For Play Equipment

Maintenance Check	Week 1	Week 2	Week 3	Week 4	Week 5
Check Rotating Parts	23/8	30/8	6/9	13/9	20/9
Check Swing Chain Links/Shackles/Seats	23/8	30/8	6/9	13/9	20/9
Check Bolts/Fixings/Ball Joints	23/8	30/8	6/9	13/9	20/9
Check For Loose/Missing Parts	23/8	30/8	6/9	13/9	20/9
Check Plastic/Rubber Parts	23/8	30/8	6/9	13/9	20/9
Check For Damage/Obstruction/Corrosion	23/8	30/8	6/9	13/9	20/9
Check Safe Surfacing	23/8	30/8	6/9	13/9	20/9
Check Fencing	23/8	30/8	6/9	13/9	20/9

Comments: The wooden decking above the steps for the tower have rotted away to form a hole.

Notes: