# **Botus Fleming Parish Council Asset Audit Report**

(This audit does not include any aspect of the Playing Field which is audited separately)

DATE OF AUDIT: 14/03/2023		AUDITED BY: S. White							
Item	Area		Condition	Action Required					
Life Belt	Moditonham Quay		Good	None					
Notes:									
Parish Pound	Botus Fleming		Good	None					
Notes:									
Bus Shelter	Hatt		No change	None					
Railings and Signage	Hatt Roundabout		No change	None					
Play Equipment	Recreation Field		See Appendix A						
Notes:									
Notice Board	Botus Fle	eming	Good	None					
	Hatt		No change	Work required					
Notes:									

## **Botus Fleming Parish Council Asset Audit Report**

(This audit does not include any aspect of the Playing Field which is audited separately)

DATE OF AUDIT: 14/03/2023		AUDITED BY: S. White								
Item	Area		Condition	Action Required						
Salt Grit Bins	Hatt Sunnybanks		1/2 Full	None						
	Hatt Vollards Lane		1/2 Full	None						
	Road, Hatt To Botus Fleming		Full	None						
	Botus Fleming Crossroads		1/4 Full	None						
Notes:										
Benches	Moditonh	am Quay	Good	None						
	Road, Hatt To Botus Fleming		Good	None						
	Recreation Field 1		No change	Watch						
	Recreation Field 2		No change	Watch						
Picnic Benches	Recreation Field		Good	None						
Notes:										
Laptop	Parish Clerk		No change	None						
Printer	Councillor/Auditor		No change	None						

### **Botus Fleming Parish Council Asset Audit Report**

(This audit does not include any aspect of the Playing Field which is audited separately)

#### Appendix A

#### Checklist For Play Equipment

Maintenance Check	Week 1	Week 2	Week 3	Week 4	Comment
Check Rotating Parts	18/2	26/2	4/3	11/3	
Check Swing Chain Links/Shackles/Seats	18/2	26/2	4/3	11/3	
Check Bolts/Fixings/Ball Joints	18/2	26/2	4/3	11/3	
Check For Loose/Missing Parts	18/2	26/2	4/3	11/3	
Check Plastic/Rubber Parts	18/2	26/2	4/3	11/3	
Check For Damage/Obstruction/Corrosion	18/2	26/2	4/3	11/3	
Check Safe Surfacing	18/2	26/2	4/3	11/3	

Notes: The annual inspection of the play equipment by Zurich, the Insurers, has taken place. The report is satisfactory with the only highlighted item being the surface under the older swings which needs the rebound status checked.