

# **Botus Fleming Parish Council Asset Audit Report**

(This audit does not include any aspect of the Playing Field which is audited separately)

DATE OF AUDIT: 14/07/2025	AUDITED BY: S. White
------------------------------	-------------------------

Item	Area	Condition	Action Required
------	------	-----------	-----------------

Life Belt	Moditonham Quay	Good	None
-----------	-----------------	------	------

Notes:
--------

Parish Pound	Botus Fleming	Good	None
--------------	---------------	------	------

Notes:
--------

Bus Shelter	Hatt	Good	None
Railings and Signage	Hatt Roundabout	No Change	None
Play Equipment	Recreation Field	See Appendix A	

Notes:
--------

Notice Board	Botus Fleming	Good	None
	Hatt	Good	None

Notes:
--------

# **Botus Fleming Parish Council Asset Audit Report**

(This audit does not include any aspect of the Playing Field which is audited separately)

DATE OF AUDIT: 14/07/2025	AUDITED BY: S. White
------------------------------	-------------------------

Item	Area	Condition	Action Required
------	------	-----------	-----------------

Salt Grit Bins	Hatt Sunnybanks	Full	None
	Hatt Vollards Lane	3/4 Full	None
	Road, Hatt To Botus Fleming	Full	None
	Botus Fleming Crossroads	Full	None

Notes:
--------

Benches	Moditonham Quay	Fair	None
	Road, Hatt To Botus Fleming	Fair	None
	Recreation Field 1	Fair	None
	Recreation Field 2	Fair	None
Picnic Benches	Recreation Field	Good	None

Notes:
--------

Laptop	Parish Clerk	No Change	None
Printer	Councillor/Auditor	No Change	None

# **Botus Fleming Parish Council Asset Audit Report**

(This audit does not include any aspect of the Playing Field which is audited separately)

## **Appendix A**

### Checklist For Play Equipment

Maintenance Check	Week 1	Week 2	Week 3	Week 4	Week 5
Check Rotating Parts	22/6	29/6	6/7	13/7	
Check Swing Chain Links/Shackles/Seats	22/6	29/6	6/7	13/7	
Check Bolts/Fixings/Ball Joints	22/6	29/6	6/7	13/7	
Check For Loose/Missing Parts	22/6	29/6	6/7	13/7	
Check Plastic/Rubber Parts	22/6	29/6	6/7	13/7	
Check For Damage/Obstruction/Corrosion	22/6	29/6	6/7	13/7	
Check Safe Surfacing	22/6	29/6	6/7	13/7	
Check Fencing	22/6	29/6	6/7	13/7	

Comments: A damaged strut on the wooden tower by the steps was repaired by Councillor Willey. Many thanks to Councillor Willey for his prompt action.

Notes: